

NT 4 Driver for PD-10401V1

Version history

Version 1.0.0.0

- First official release

Version 1.0.0.2

- Minor internal modifications

Version 1.0.0.4

- Internal changes

Version 1.0.0.8

- Internal optimizations
- Implemented asynchronous modes
- Fixed bug which caused the last spectrum of a burst to be zero
- Removed debug operations resulting in access to DOUT1 during spectral acquisition

Version 1.0.1.0

- Fixed bug related with the MMS-NIR-LX sensor
- Timing for I2C controller access optimised, this will solve some problems with faster CPUs and chipsets