

WDM Driver for PD-10401V1

Version history

Version 1.0.0.0

- § First official release

Version 1.0.0.2

- § Minor internal modifications

Version 1.0.0.4

- § Internal changes

Version 1.0.0.6

- § Internal optimizations
- § Implemented asynchronous modes

Version 1.0.0.8

- § Fixed bug which caused the last spectrum of a burst to be zero
- § Removed debug operations resulting in access to DOUT1 during spectral acquisition

Version 1.0.1.0

- § Fixed bug related with the MMS-NIR-LX sensor
- § Timing for I2C controller access optimised, this will solve some problems with faster CPUs and chipsets